

ATLANTA MEMORIAL PARK

January 16, 2014

HGOR



Restore Peachtree & Tanyard Creeks along with Providing Flood Mitigation

Revitalize Memorial Park

Enhance Neighborhood Connectivity

Renovate Bobby Jones Golf Course

Renovate Bobby Jones Clubhouse

Incorporate effort with current renovations at Bitsy Grant Tennis Center

HIGHLIGHTS FROM WORKSHOP 1

HGOR



Connectivity & Greenspace

Safety

Long-term Management

18 Holes of Golf

Expanded Tennis

Possible Clustering of Golf & Tennis Proshops

Alternative Community Use of Existing Historical Clubhouse



Preservation and creation of additional passive green space

Connectivity to surrounding areas & trails

Pedestrian trail system

-> Attention to selection of path materials

Create Golf & Tennis Pro shop at Bitsy Grant

Co-located golf & tennis parking at expanded Bitsy Grant

Support for maintaining Woodward & pedestrian connectivity through raised Northside bridge



Support of a connected passive park around golf and tennis

Trails with safe lighting and material to allow all types of users

Future use of Historic Club House


Long term maintenance and management plan for the park

Remove invasives, restore native species, stormwater management

Support for maintaining Woodward & pedestrian connectivity through raised Northside bridge


TRAILS AND CONNECTIVITY - PARK

HGOR




AMP TREE CANOPY CLASSIFICATIONS

HGOR











EXISTING TREE IMAGES

HGOR



SHADE TREES IN TURF TYPICAL OF **OPEN TREE LAWNS**



VERY CLOSE TREE SPACING



TYPICAL PINE TREE SPACING










DENSE SPACING LEADS TO WEAK STRUCTURED YOUNG TREES THAT LEAN

HARDWOODS ALONG PEACHTREE CREEK WITH ABUNDANT DEAD WOOD

TRAIL SURFACE CHARACTER IMAGES

HGOR



GRANITE FINES

ASPHALT



POROUS PAVEMENT



CONCRETE



MULCH



RUBBER